

August 08, 2001

, Inc.

New Hampshire Ave
Silver Spring, MD 20904

Stormwater Facility #: 1608 Property Address: New Hampshire Ave

Dear Homeowners Association President or Property Manager:

The Department of Environmental Protection (DEP) through its contractor has inspected your stormwater management structure. A list of the necessary repairs of the facility as a result of that inspection is attached. The next step in repairing your facility would be to get bids and a scope of work from several contractors and then hire a contractor to perform the necessary work. You may use any contractor who can meet the regulatory requirements of the job. We have compiled the attached list of contractors as a service, because of the number of requests we receive for this information. DEP does not recommend any contractor.

Once you have a contractor, you must contact DEP inspection staff, or
at (240) or (240) , respectively, to arrange a site visit to discuss the repairs. Then, Mike or Steve will make a final approval inspection once the repairs are completed.

It is possible that county and state water quality permits will need to be issued prior to the start of the repair project. You may need to contact an engineer or other qualified persons to prepare site plans or other documents for these permits. If you have questions concerning the permitting process, you should contact the Department of Permitting Services at (240) 777-6360.

You have 120 days from receipt of this letter to make the repairs and have a satisfactory final approval inspection. We will make every effort to assist you in this process but failure to complete the repairs in the specified time will result in enforcement action being taken against you in accordance with Chapter 19 of the Montgomery County Code and Executive Regulation 5-90. If you have questions regarding the inspection, please contact me at (240) - .

Sincerely,

Attachment

Senior Planning Specialist

Senior Planning Specialist

Homeowners Association President or Property Manager

Stormwater Facility Number: 1608 Inspection Date: 06/26/2001

Page 2

List of Repairs

Repairs - Below are items that were noted on the inspection sheet as needing repair

- Riser / weir wall / control structure
Mow around riser. Install steps into riser. Remove small trees from around low flow.
- Forbay
- Low flow orifice(s)
Remove small trees from around low flow.
- Other underground drains
- Internal embankment drains
- Sediment loads
- Pond inlet structures and embankments
Remove trees from west infall to pond.
- Outlet(s) from pond: headwalls, rip-rap channels
Outfalls to stormdrain system.
- Speciality structures such as flow splitters
- Principal spillway barrel(s)
18 inch barrel was not entered.
- Valves/orifices/pond drains
- Other / miscellaneous items
- Dam structure and emergency spillway
Remove small trees from upstream dam bank and mow. Monitor landscaped trees on downstream dam bank toe.